

Port Aransas Historic Resources Survey, Nueces County, Texas

Inventory of Properties

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
123 S 10th Street	113	Low	1930	Building	Dwelling	Front Gable	Vertical Hardboard		porch altered, aluminum windows
			1965	Domestic	Dwelling		Good	1	
300 block S 10th Street	114	Low	1940	Building	Warehouse	Front Gable	Metal		cold storage
				Commercial	Vacant		Fair	1	
300 block S 10th Street	115	Low	1950	Building	Storage building	Flat	CMU		concrete warehouse/storage in trailer park
				Domestic	Storage building		Fair	1	
400 block S 10th Street	116	Medium	1930	Building	Vacation Cottages	Side Gable	Asbestos		Sea & Sand Cottages. address of office is 221 E. Ave. E, but that building (# 51) is a low priority and is not photographed
				Domestic	Vacation Cottages		Good	1	
404 S 10th Street	117	High	1930	Building	Dwelling	Cross Gable	Asbestos		original windows and entries, 4/4 windows, triangular knee braces
				Domestic	Dwelling	Craftsman	Good	1	
505? S 10th Street	118	Medium	1930	Building	Dwelling	Side Gable	Asbestos		has side porch
				Domestic	Dwelling		Good	1	
511 S 10th Street	119	High	1920	Building	Dwelling	Hip	Asbestos		hip porch on hip roof, 4/4 windows, exposed rafters, high integrity
				Domestic	Dwelling	Craftsman	Fair	1	
515 S 10th Street	120	Medium	1930	Building	Dwelling	Side Gable	Asbestos		louvered windows
				Domestic	Dwelling		Fair	1	
524 S 10th Street	122	Low	1955	Building	Dwelling	Flat	Stucco		flat roofed apartment in the yard of #123, but addressed differently
				Domestic	Dwelling		Good	1	
525 S 10th Street	121	Low	1935	Building	Dwelling	Side Gable	Wood		alterations, wood front deck
			1980	Domestic	Dwelling		Good	1	
526 S 10th Street	123	Medium	1930	Building	Dwelling	Front Gable	Vinyl		rustic porch posts and railing (replaced)
			1975	Domestic	Dwelling	Craftsman	Good	1	
100 block S 11th Street	90	Low	1960	Building	Dwelling	Side Gable	Asbestos		addressed on Ave. B but fronts 11th Street. multiple alterations, second story deck
				Domestic	Dwelling		Excellent	2	
100 block S 11th Street	142	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		paired 1/1 windows, rear addition
				Domestic	Dwelling	Minimal Traditional	Good	1	
200 S 11th Street	143	Low	1940	Building	Dwelling	Cross Gable	Asbestos		additions and alterations
			1970	Domestic	Dwelling		Good	1	
218 S 11th Street	144	Medium	1950	Building	Dwelling	Cross Gable	Asbestos		2 or more small houses?
				Domestic	Dwelling		Excellent	1	
227 S 11th Street	145	Medium	1940	Building	Dwelling	Side Gable	Stucco		replaced windows, triangle knee braces, stoop entry
				Domestic	Dwelling		Good	1	
100 block S 12th Street	99	Low	1955	Building	Dwelling	Hip	Asbestos/Wood		big addition on street side
			1975	Domestic	Dwelling		Fair	1	
129 S 12th Street	98	Medium	1955	Building	Dwelling	Front Gabled Bungalow	Wood		screened front gabled porch. address on 12th Street is a side entry; front of house faces Jill's Way
				Domestic	Dwelling		Good	1	
230 S 12th Street	96	Medium	1960	Building	Dwelling	Cross Gable	Asbestos		big picture windows
				Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
246 S 12th Street	95	Medium	1955	Building	Dwelling	Front Gable and Side Gable	Asbestos		two attached houses--larger, side-gabled house has two stories and a full screened porch on its upper story; front-gabled house has one story
			1975	Domestic	Dwelling		Good	2	
307 S 12th Street	97	Medium	1960	Building	Dwelling	Cross Hip	Asbestos		rambling; brick chimney
				Domestic	Dwelling	Ranch	Excellent	1	
400 block S 12th Street	165	Medium	1940	Building	Dwelling	Hip	Wood		Summer Place. 1- and 2-story sections, nice window trim, renovated, many new replacements. basement garage
			1995	Domestic	Dwelling	Prairie	Excellent	2	
500 block S 12th Street	94	Low	1960	Building	Dwelling	Hip	Asbestos		front addition and front porch addition
				Domestic	Dwelling		Good	2	
528 S 12th Street	93	Low	1960	Building	Dwelling	Hip	Wood		porch supported by poles
				Domestic	Dwelling		Fair	2	
500 block S 9th Street	112	Low	1930	Building	Dwelling	Flat	Asbestos		porch addition, roof flattened
			1960	Domestic	Retail		Fair	1	
519 S 9th Street	111	Medium	1925	Building	Dwelling	Front Gable	Masonite?		Victorian turned posts, piers not original, 1/1 windows
			2000	Domestic	Dwelling	Craftsman	Excellent	1	
100 block N Alister Street	109	Medium	1960	Building	Tourist Court	Flat	CMU		The Village
				Domestic	Multi-Unit Dwelling	Modern	Good	1	
104 N Alister Street	108	Medium	1925	Building	Dwelling	Cross Gable	Wood		small house turned office for Sportsman Lodge
			1932	Domestic	Office		Good	1	
115 N Alister Street	107	High	1954	Building	Retail	Complex	Wood/Metal		Billmore Hardware. still in use as hardware store. metal awning
			1970	Commercial	Retail		Good	1	
202 N Alister Street	106	Medium	1925	Building	Dwelling	Shotgun	Asbestos		now a tattoo parlor
				Domestic	Retail		Good	1	
300 block N Alister Street	5	Low	1955	Building	Dwelling	Side Gable	Asbestos		now a series of small shops
				Domestic	Retail		Good	1	
340 N Alister Street	8	High	1930	Building	Tourist Court	Side Gable	Wood		Gibbs Cottages. large 2-story building with hipped roof and a series of 1-story tourist cottages on the same lot.
				Domestic	Vacant	Craftsman	Good	2	
400 block N Alister Street	68	Medium	1949	Building	Community Center	Side Gable	Wood		community center. possible 1965 addition
			1965	Civic	Community Center		Good	1	
403 N Alister Street	2	Medium	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends
				Domestic	Vacant	Craftsman	Good	1	
403 B N Alister Street	3	Low	1935	Building	Dwelling	Front Gable	Asbestos		clipped gable
			1980	Domestic	Vacant	Craftsman	Fair	1	
403 C N Alister Street	4	Low	1935	Building	Dwelling	Front Gable	Asbestos		exposed rafter ends
			1985	Domestic	Retail	Craftsman	Good	1	
500 block N Alister Street	105	Medium	1960	Building	Auto Service	Flat	CMU		projecting awning, garage bays
				Commercial	Auto Service		Good	1	
100 block S Alister Street	40	High	1920	Building	Church	Complex	Hardiplank		original stained glass, turret
			1990	Religious	Church	Gothic	Excellent		
100 block S Avenue A	60	Low	1950	Building	Tourist Court	Flat	Asbestos		
				Domestic	Tourist Court		Fair	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
100 block S Avenue A	61	Low	1955	Building	Dwelling	Front Gable	Wood		front addition, louvered windows
			1980	Domestic	Dwelling		Good	1	
300 block E Avenue B	89	Low	1960	Building	Tourist Court	Shed	Asbestos		8 small apartments
				Domestic	Multi-Unit Dwelling		Fair	1	
319 E Avenue B	59	Low	1945	Building	Dwelling	Hip with Gable	Asbestos		1/1 windows, louvered blinds
				Domestic	Dwelling		Fair	1	
505 E Avenue B	58	Medium	1935	Building	Dwelling	Front Gable and Side Gable	Asbestos		two Bungalows stuck together
				Domestic	Dwelling		Excellent	1	
619 E Avenue B	57	Low	1935	Building	Dwelling	Cross Gable	Asbestos/Wood		fire victim. triangular knee braces, shuttered windows
				Domestic	Dwelling	Craftsman	Poor	1	
620 A E Avenue B	41 A	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		moved from the flats in 1938
				Domestic	Dwelling	Craftsman	Good	1	
620 B E Avenue B	41 B	High	1938	Building	Chapel	Pyramidal	Stucco		Carter Chapel/the Chapel on the Dunes. interior painted in the late 1970s by painter John Patrick Cobb. some recent minor alterations
				Religious	Chapel		Good	1	
639 A E Avenue B	42 A	Medium	1935	Building	Dwelling	Hip	Asbestos		windows replaced
			1990	Domestic	Dwelling	Craftsman	Excellent	1	
639 B E Avenue B	42 B	Medium	1930	Building	School	Front Gable	Asbestos		6/6 windows, exposed rafter ends. attached to #42 A
				Education	Dwelling	Craftsman	Good	1	
126 E Avenue C	44	Medium	1945	Building	Dwelling	Side Gable	Asbestos/Wood		aluminum windows, replaced door
				Domestic	Dwelling		Good	1	
225 E Avenue C	56	Medium	1935	Building	Dwelling	Front Gable	Asbestos		clipped gable, triangular knee braces, exposed rafter ends
			1970	Domestic	Dwelling	Craftsman	Good	1	
507 E Avenue C	55	Low	1955	Building	Dwelling	Front Gable	Asbestos		porch detracts
			1970	Domestic	Dwelling		Fair	1	
508 E Avenue C	43	Medium	1950	Building	Dwelling	Front Gable	Asbestos		louvered windows
				Domestic	Dwelling		Good	1	
603 E Avenue C	54	Medium	1955	Building	Dwelling	Cross Gable	Asbestos/Wood		paired windows
				Domestic	Dwelling		Good	1	
221 E Avenue E	51	Low	1955	Building	Dwelling	Front Gable	Wood		front and side additions
			1970	Domestic	Multi-unit Dwelling		Good	1	
309 E Avenue E	52	Low	1955	Building	Dwelling	Front Gable	Asbestos/Wood		faux bay window
			1980	Domestic	Dwelling		Good	1	
316 E Avenue E	91	Medium	1950	Building	Dwelling	Front Gable	Asbestos		side addition
				Domestic	Dwelling		Good	1	
107 E Avenue F	50	Medium	1955	Building	Vacation Cottages	Side Gable	Asbestos		duplex with full-face porch
				Domestic	Vacation Cottages		Good	1	
115 E Avenue F	49	Medium	1940	Building	Dwelling	Cross Gable	Wood		porch posts are 4x4s
			1985	Domestic	Dwelling	Craftsman	Good	1	
122 E Avenue F	46	Low	1955	Building	Dwelling	Side Gable	Wood		has addition and replaced wood
			1965	Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
128 E Avenue F	47	Low	1955	Building	Dwelling	Side Gable	Wood		huge A-frame added
			1970	Domestic	Dwelling		Good	2	
131 E Avenue F	48	Medium	1950	Building	Dwelling	Cross Gable	Wood		cottage with 8/8 windows
				Domestic	Dwelling		Good	1	
200 block E Avenue F	92	Medium	1960	Building	Tourist Court	Flat	CMU		Deco concrete apartments
				Domestic	Multi-Unit Dwelling	Modern	Fair	1	
205 E Avenue F	110	Medium	1925	Building	Dwelling	Side Gable	Board and Batten		60s aluminum windows
			1960	Domestic	Dwelling		Fair	1	
415 E Avenue G	147	Medium	1960	Building	Vacation Cottages	Front Gable	Vertical Hardboard		paired 1/1 windows. Double Barr tourist cottages
				Domestic	Vacation Cottages		Good	1	
503 E Avenue G	146	Medium	1945	Building	Tourist Court	Flat	Hollow Tile		Laughing Horse tourist court
				Domestic	Tourist Court		Good	1	
603 E Avenue G	45	High	1940	Building	Tourist Court	Front Gable	Rock		Rock Cottages. 6/6 windows, honeycombed rock wth wide mortar joints
			1970	Domestic	Tourist Court	CCC	Good	1	
618 E Avenue G	166	Medium	1920	Building	Dwelling	Cross Gable	Wood		
			1970	Domestic	Multi-Unit Dwelling		Fair	1.5	
118 E Beach Street	85	Low	1960	Building	Dwelling	Hexagonal/Hip	Hardboard		possibly resurfaced
				Domestic	Vacant		Poor	1	
200 block E Beach Street	16	Low	1935	Building	Dwelling	Mansard	Wood		mansard front on front-gabled Bungalow with front-gabled porch
			1975	Domestic	Retail		Good	1	
208 E Beach Street	86	Low	1950	Building	Dwelling	Front Gable	Asbestos/Hardboard		enclosed porch with window display
			1965	Domestic	Retail		Good	1	
212 E Beach Street	87	Low	1960	Building	Unknown	Front Gable	Asbestos		infilled windows, replaced door
			1975	Civic	Vacant		Fair	1	
216? E Beach Street	88	Low	1945	Building	Dwelling	Front Gable	Wood		attached garage, aluminum replacement windows
				Domestic	Vacant		Poor	1	
229 B E Beach Street	17	Low	1960	Building	Dwelling	Front Gable	Wood		likely a manufactured home, paired 1/1
				Domestic	Dwelling		Fair	1	
200 block E Brown Avenue	102	Low	1975	Building	Dwelling	Front Gable	Hardboard		3 apartments; possibly originally a house with secondary dwelling or outbuilding?
				Domestic	Multi-Unit Dwelling		Excellent	1	
228 E Brown Avenue	101	Low	1940	Building	Dwelling	Cross Gable	Hardiplank		louvered windows and doors
			1960	Domestic	Dwelling		Good	1	
200 block E Brundrett Avenue	28	High	1960	Building	Church	Front Gable	Brick		good example of type; door protected
				Religious	Church	Modern	Excellent	1	
211 E Brundrett Avenue	29	Low	1960	Building	Dwelling	Hip	Asbestos		new metal roof, massive posts
				Domestic	Dwelling		Fair	2	
217 E Brundrett Avenue	30	High	1930	Building	Dwelling	Front Gable	Asbestos		very good example, louvered windows
				Domestic	Dwelling	Craftsman	Excellent	1	
224 E Brundrett Avenue	84	Medium	1935	Building	Dwelling	Hip	Asbestos		hip porch, 1/1 windows, exposed rafters
				Domestic	Dwelling	Craftsman	Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
128 A W Brundrett Avenue	24	Medium	1935	Building	Dwelling	Front Gable	Asbestos		4/1 and 1/1 windows, porch added or replaced circa 1960
			1960	Domestic	Dwelling	Craftsman	Good	1	
128 B W Brundrett Avenue	24 B	Medium	1935	Building	Garage	Front Gable	Asbestos		Hasp-hung door, multi-light windows
				Domestic	Vacant	Craftsman	Poor	1	
132 W Brundrett Avenue	25	Medium	1930	Building	Dwelling	Hip	Asbestos		hip with hip porch
				Domestic	Dwelling	Craftsman	Fair	1	
16 W Brundrett Avenue	26	Low	1930	Building	Dwelling	Side Gable	Asbestos		front-gabled porch
			1960	Domestic	Dwelling	Craftsman	Good	1	
17 W Brundrett Avenue	27	Low	1935	Building	Dwelling	Front Gable	Asbestos		enclosed porch
			1960	Domestic	Dwelling	Craftsman	Good	1	
320 E Channel View Drive	186	Low	1940	Building	Dwelling	Front Gable	Vertical Hardboard		1/1 windows, plain
				Domestic	Dwelling		Good	1	
326 E Channel View Drive	187	Medium	1940	Building	Dwelling	Front Gable	Asbestos		exposed rafter ends
			1970	Domestic	Dwelling	Craftsman	Fair	1	
327 E Channel View Drive	188	Low	1960	Building	Dwelling	Flat	Asbestos		no-frills "modern cottage"
				Domestic	Dwelling	Modern	Good	1	
410 E Channel View Drive	189	Low	1930	Building	Dwelling	Complex	Wood		initially a small Bungalow; big 1970s 2-story addition
			1975	Domestic	Dwelling	Craftsman/Contemporary	Good	2	
417 E Channel View Drive	192	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		1/1 windows, exposed rafter ends, brick chimney
				Domestic	Dwelling	Craftsman	Good	1	
624 E Channel View Drive	191	Medium	1955	Building	Dwelling	Side Gable	Asbestos		elevated, 2nd story porch
			1965	Domestic	Dwelling		Excellent	2	
732 E Channel View Drive	190	Medium	1955	Building	Dwelling	Side Gable	Asbestos		wide screened porches on both floors, upper floor deck added
			1965	Domestic	Dwelling		Excellent	2	
206 S Church Street	67	Medium	1960	Building	Dwelling	Cross Gable	Wood		louvered windows
				Domestic	Dwelling	Ranch	Good	1	
207 S Church Street	6	Medium	1930	Building	Dwelling	Front Gable	Vinyl		6/6 windows, no porch
			1985	Domestic	Dwelling	Craftsman	Good	1	
213 S Church Street	7	Medium	1935	Building	Dwelling	Front Gable	Asphalt		horizontal aluminum windows
			1965	Domestic	Dwelling		Good	1	
106 E Cotter Avenue	160	High	1920	Building	Retail	Cross Gable	Asbestos		The Big Kahuna restaurant. Picture windows. rare surviving historic commercial building
			1960	Commercial	Restaurant		Good	1	
200 E Cotter Avenue	161	High	1925	Building	Inn	Hip	Wood		Tarpon Inn. box columns, veranda. renovated. rare surviving historic inn--restaurant wing dates to 1904, main volume to 1925.
				Domestic	Inn	Classical/Craftsman	Excellent	2	
319 E Cotter Avenue	162	Low	1930	Building	Dwelling	Flat	Wood		replaced sliding windows
			1960	Domestic	Dwelling		Good	1	
326 E Cotter Avenue	163	Low	1930	Building	Dwelling	Side Gable	Wood		big addition on front side
			1980	Domestic	Dwelling		Good	1	
329 E Cotter Avenue	164	Low	1935	Building	Dwelling	Side Gable	Wood		clipped gable, big front additions
			1970	Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
500 block E Cotter Avenue	175	Low	1935	Building	Dwelling	Front Gable	Asbestos		decks and additional 2nd-floor entry added
			1965	Domestic	Dwelling	Craftsman	Good	2	
525 E Cotter Avenue	174	Medium	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends, 1/1 windows
				Domestic	Dwelling	Craftsman	Good	1	
428 E Lantana Drive	167	Medium	1925	Building	Dwelling	Front Gabled Bungalow	Wood (false bevel)		turned porch posts are Folk Victorian
			1995	Domestic	Dwelling	Craftsman	Excellent	1	
500 E Lantana Drive	168	Medium	1950	Building	Dwelling	Hip	Asbestos		shuttered windows, cupola, no porch
			1980	Domestic	Dwelling	Prairie	Excellent	1	
513 E Lantana Drive	169	Medium	1930	Building	Dwelling	Cross Gable	Asbestos		porch with 4x4 posts added. Bungalow windows
			1960	Domestic	Dwelling		Good	1	
518 E Lantana Drive	171	Medium	1960	Building	Dwelling	Flat	Asbestos/Wood		louvered windows. porch added
				Domestic	Dwelling	Modern	Good	1	
523 E Lantana Drive	170	Low	1960	Building	Duplex	Side Gable	Asbestos/Wood		aluminum windows
				Domestic	Duplex		Good	1	
400 block N Mercer Street	62	Low	1940	Building	Dwelling	Side Gable	Asbestos		multiple additions
				Domestic	Dwelling		Fair	1	
407 N Mercer Street	39	Medium	1930	Building	Dwelling	Side Gable	Asbestos		clipped gables, dormers added
			1975	Domestic	Dwelling	Craftsman	Fair	1.5	
442 N Mercer Street	63	Low	1955	Building	Dwelling	Side Gable	Asbestos		louvered doors and windows
				Domestic	Dwelling		Fair	1	
509 N Mercer Street	38	Medium	1960	Building	Dwelling	Flat	Wood		casement and louvered windows
				Domestic	Dwelling	Modern	Excellent	1	
203 E Oakes Avenue	36	Medium	1920	Building	Dwelling	Cross Gable	Wood (false bevel)		under renovation
			2006	Domestic	Dwelling		Poor	1	
205 E Oakes Avenue	35	Low	1955	Building	Dwelling	Side Gable	Wood		big front addition and porch
			1970	Domestic	Dwelling		Fair	1	
206 E Oakes Avenue	78	Low	1940	Building	Parsonage	Side Gable	Cement Stucco		may be a parsonage. in church yard (see #79)
			1975	Religious	Parsonage		Good	1	
208 E Oakes Avenue	79	High	1915	Building	Church	Front Gable	Asbestos		St. Joseph's Catholic Church. now a residence. multi-light windows
				Religious	Church	Gothic	Good	1.5	
209 E Oakes Avenue	34	Medium	1940	Building	Dwelling	Front Gable	Wood		late Bungalow. paired windows
				Domestic	Dwelling		Good	1	
220 E Oakes Avenue	80	Low	1955	Building	Dwelling	Front Gable	CMU		main entry enclosed; entry stoop
			1970	Domestic	Dwelling		Good	1	
221 E Oakes Avenue	33	Low	1930	Building	Dwelling	Hip	Asbestos		side front addition, louvered windows
			1960	Domestic	Dwelling	Craftsman	Fair	1	
232 E Oakes Avenue	10	Medium	1930	Building	Dwelling	Cross Gable	Wood		clipped gable with clipped gable porch
				Domestic	Dwelling	Craftsman	Good	1	
233 E Oakes Avenue	103	Low	1930	Building	Dwelling	Cross Hip	Hardboard		left half is hardboard
			1950	Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
300 block E Oakes Avenue	81	High	1891	Site	Cemetery		Stone		Mercer Cemetery. about 7-8 headstones, some of which found when land leveled for school track.
				Funerary	Cemetery		Good		
320 E Oakes Avenue	82	Low	1930	Building	Dwelling	Side Gable	Wood		aluminum windows; porch enclosed
			1965	Domestic	Dwelling		Fair	1.5	
321 E Oakes Avenue	32	Low	1935	Building	Dwelling	Cross Gable	Asbestos		enclosed porch, front addition
			1960	Domestic	Dwelling	Craftsman	Good	1	
322 E Oakes Avenue	83	Low	1940	Building	Dwelling	Front Gable	Stucco		aluminum windows; exposed rafters
			1965	Domestic	Dwelling		Fair	1	
325 E Oakes Avenue	31	High	1930	Building	Dwelling	Cross Gable	Asbestos		paired windows
				Domestic	Dwelling	Tudor Revival	Excellent	1	
124 W Oakes Avenue	37	Low	1940	Building	Dwelling	Front Gable	Wood/CMU		Bungalow with hipped addition
			1950	Domestic	Commercial		Fair	1	
125? W Oakes Avenue	77	Low	1955	Building	Dwelling	Cross Gable	Wood		shiplap siding, aluminum windows replaced
			1970	Domestic	Dwelling		Good	1	
200 block N Oleander Street	69	Low	1960	Building	Tourist Court	Side Gable	Wood		tourist court or tourist apartments
				Domestic	Tourist Court		Fair	1	
218 N Oleander Street	70	Low	1935	Building	Dwelling	Hip	Aluminum		big side addition
			1970	Domestic	Dwelling		Fair	1	
600 block N Oleander Street	104	Medium	1925	Building	Retail	Side Gable	Wood		Brundrett Taxidermy, porch supported by driftwood
				Commercial	Retail		Fair	2	
200 block S Oleander Street	1	High	1915	Building	Dwelling	Side Gable	Wood (false bevel)		Sears house. low gables, hipped dormer, high integrity
			1980	Domestic	Vacant	Classical/Colonial Revival	Good	1.5	
400 block E Palm Drive	173	Low	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafters, big carport added
			1965	Domestic	Dwelling		Fair	1	
432 E Palm Drive	172	Medium	1935	Building	Dwelling	Cross Gable	Wood/Vertical Hardboard		louvered windows, exposed rafter ends, triangular knee braces
			1965	Domestic	Dwelling	Craftsman	Good	1	
106 E Roberts Avenue	100	Medium	1950	Building	Retail	Front Gable with Parapet	Wood		parapet likely new
			1995	Commercial	Retail		Good	1	
200 E Roberts Avenue	66	Medium	1935	Building	Dwelling	Hip with Gable	Asbestos		gabled porch, louvered windows
				Domestic	Dwelling	Craftsman	Good	1	
207 E Roberts Avenue	22	Medium	1945	Building	Dwelling	Hip with Gables	Asbestos		louvered windows, entry porch
				Domestic	Dwelling		Excellent	1	
219 E Roberts Avenue	21	Medium	1930	Building	Dwelling	Front Gable	Wood/Hardboard		aluminum windows, porch enclosed
			1960	Domestic	Dwelling		Fair	1	
224 E Roberts Avenue	75	Low	1940	Building	Dwelling	Side Gable	Asbestos		paired windows, screened porch
			1960	Domestic	Dwelling		Good	1	
227 E Roberts Avenue	20	Medium	1960	Building	Dwelling	Front Gable	Wood/Hardboard		aluminum windows
				Domestic	Dwelling		Good	1	
230 E Roberts Avenue	76	Low	1945	Building	Dwelling	Front Gable	Asbestos		scrollwork porch post "capitals," new windows
			2000	Domestic	Dwelling	Craftsman/Folk Victorian	Excellent	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
317 E Roberts Avenue	18	Medium	1960	Building	Dwelling	Front Gable	CMU		decorative wood in gable end
				Domestic	Dwelling		Good	1	
319? E Roberts Avenue	19	Low	1940	Building	Dwelling	Front Gable	Wood		multiple additions
			1960	Domestic	Dwelling		Fair	1	
100 block W Roberts Avenue	72	Medium	1930	Building	Dwelling	Cross Hip	Asbestos		new roof
			1995	Domestic	Dwelling		Good	1	
113 W Roberts Avenue	74	Medium	1935	Building	Dwelling	Side Gable	Wood		front deck, triangular knee braces on stoop porch roof
				Domestic	Dwelling		Good	1	
119 W Roberts Avenue	73	Medium	1930	Building	Dwelling	Cross Gable	Asbestos		exposed rafter ends, original screens
				Domestic	Dwelling	Craftsman	Good	1	
141 W Roberts Avenue	71	Medium	1935	Building	Dwelling	Side Gable	Asbestos		paired 1/1 windows, stoop porch
				Domestic	Dwelling		Good	1	
146 W Roberts Avenue	23	Medium	1935	Building	Dwelling	Cross Hip	Asbestos		paired 1/1 windows, screened porch
				Domestic	Dwelling		Fair	1	
300 block N Station Street	9	Medium	1955	Building	Dwelling	Front Gable	CMU/Wood		may be part of Lister's Cottages. paired 1/1, decorative wood gable
				Domestic	Dwelling		Good	1	
300 block N Station Street	65	Low	1940	Building	Dwelling	Cross Gable	Asbestos		replaced windows and door
				Domestic	Dwelling	Craftsman	Poor	1	
400 block N Station Street	11	Low	1930	Building	Dwelling	Front Gable	Asbestos		1/1 paired, exposed rafter ends, has matching shed
				Domestic	Vacant	Craftsman	Poor	1	
438 N Station Street	64	Low	1955	Building	Dwelling	Front Gable	Asbestos		replaced windows, lattice porch
				Domestic	Dwelling		Fair	1	
503 N Station Street	12	Medium	1955	Building	Dwelling	Front Gable	Asbestos		side addition, aluminum windows
			1965	Domestic	Dwelling		Good	1	
507 N Station Street	13	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		cross-hip roof, replaced porch, louvered window
			1965	Domestic	Dwelling	Craftsman	Good	1	
515 N Station Street	15	Low	1950	Building	Dwelling	Front Gable	Vinyl		replaced windows, 4x4 posts
				Domestic	Dwelling		Fair	1	
611 N Station Street	14	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		originally a hipped porch, paired windows
				Domestic	Dwelling	Craftsman	Good	1	
109 S Station Street	141	Low	1960	Building	Dwelling	Flat	Asbestos		typical example
				Domestic	Dwelling		Fair	1	
208 A? S Station Street	140 A	Low	1945	Building	Dwelling	Side Gable	Asbestos		front house; see #s 140B and 140C
				Domestic	Dwelling		Good	1	
208 B? S Station Street	140 B	Medium	1930	Building	Dwelling	Front Gable	Wood		house behind #140A
				Domestic	Dwelling		Fair	1	
208 C? S Station Street	140 C	Low	1930	Building	Garage	Front Gable	Wood?		garage with wood shingles; see #s 140A & 140B
				Domestic	Garage		Poor	1	
211? S Station Street	138	Low	1940	Building	Dwelling	Side Gable	Vertical Hardboard		late Bungalow
				Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
215 S Station Street	139	Low	1940	Building	Dwelling	Front Gable	Asbestos/Brick		altered Bungalow
			1960	Domestic	Dwelling		Good	1	
312 S Station Street	137	Medium	1930	Building	Dwelling	Side Gable	Asbestos		exposed rafters, 1/1 and 6/6 windows
				Domestic	Dwelling	Craftsman	Fair	1	
318 S Station Street	136	Medium	1930	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends
				Domestic	Dwelling	Craftsman	Fair	1	
412 A S Station Street	133	High	1935	Building	Dwelling	Cross Gable	Asbestos		paired 1/1 windows, high integrity
				Domestic	Dwelling	Craftsman	Good	1	
412 B S Station Street	134	Medium	1930	Building	Dwelling	Side Gabled Bungalow	Wood		could be new, metal roof, new windows
			2000	Domestic	Dwelling	Craftsman	Excellent	1	
414 B? S Station Street	135 B	Low	1935	Building	Dwelling	Side Gable	Unknown		hidden behind #135
				Domestic	Dwelling		Fair	1	
414? S Station Street	135	Medium	1930	Building	Dwelling	Cross Gable	Wood		entry porch, replaced door, louvered windows
				Domestic	Dwelling	Craftsman	Good	1	
418 S Station Street	132	Medium	1935	Building	Dwelling	Front Gable	Vertical Hardboard		paired 1/1 windows
			1950	Domestic	Dwelling		Fair	1	
500 block S Station Street	128	Medium	1935	Building	Dwelling	Side Gable	Aluminum?		couldn't see properly to photograph
				Domestic	Dwelling		Good	1	
501? S Station Street	131	Low	1940	Building	Dwelling	Front Gable	Wood/Hardboard		porches and added decoration detract
			1990	Domestic	Dwelling		Good	1	
506 S Station Street	129	Low	1940	Building	Dwelling	Front Gable	Asbestos		multiple additions, pergola detracts
			2000	Domestic	Dwelling		Good	1	
507 S Station Street	130	Medium	1935	Building	Dwelling	Front Gable	Wood (false bevel)		clipped gable, windows changed
			1970	Domestic	Dwelling	Craftsman	Good	1	
522 S Station Street	127	Medium	1940	Building	Dwelling	Side Gable	Vinyl		louvered windows
			1990	Domestic	Dwelling		Excellent	1	
600 block S Station Street	125	Low	1940	Building	Dwelling	Side Gable	Vinyl		has long addition
			1995	Domestic	Dwelling		Excellent	1	
603? S Station Street	126	Medium	1930	Building	Dwelling	Side Gable	Asbestos		small cottage with 1/1 windows
				Domestic	Dwelling		Fair	1	
604 S Station Street	124	Medium	1940	Building	Dwelling	Flat	Asbestos		paired 6/6 windows, upper story porch with rustic posts and railing
			1975	Domestic	Dwelling	Craftsman	Good	2	
322 E Tarrant Avenue	185	Medium	1940	Building	Dwelling	Side Gable	Wood/Screen		exposed rafters, long screened porch
			1960	Domestic	Dwelling		Good	1	
401 E Tarrant Avenue	183	Low	1935	Building	Dwelling	Front Gable	Wood		big picture window added, windows replaced, likely moved to site
			1975	Domestic	Dwelling	Craftsman	Good	1	
402 E Tarrant Avenue	184	Low	1945	Building	Dwelling	Side Gable	Wood/CMU		multiple additions
			1960	Domestic	Dwelling		Fair	1	
413 E Tarrant Avenue	182	Low	1980	Building	Dwelling	Front Gable	Vertical Hardboard		possibly 1980s with historic references. hipped porch, shuttered windows
				Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
419 E Tarrant Avenue	181	Low	1945	Building	Dwelling	Front Gable	Wood?		altered windows
				Domestic	Dwelling		Good	1	
612 E Tarrant Avenue	180	Medium	1940	Building	Dwelling	Hip	Asbestos		elevated, louvered windows
				Domestic	Dwelling	Craftsman	Good	2	
622 E Tarrant Avenue	179	Medium	1935	Building	Dwelling	Hip	Asbestos		cross hip, elevated, 1/1 windows
			1960	Domestic	Dwelling	Craftsman	Good	2	
700 block E Tarrant Avenue	177	Medium	1960	Building	Dwelling	Side Gable	Wood/Asbestos/Brick		house has angled section, roof flares at gable ends, aluminum windows
				Domestic	Dwelling	Modern	Good	2	
706 E Tarrant Avenue	178	Medium	1940	Building	Dwelling	Hip	Asbestos		elevated over garage, 1/1 windows, deck added
			1960	Domestic	Dwelling	Craftsman	Good	2	
747 E Tarrant Avenue	176	Medium	1935	Building	Dwelling	Hip	Asbestos		elevated over garage, paired and tripled windows, exposed rafter ends
			1960	Domestic	Dwelling	Craftsman	Good	2	
324 S Trojan Street	149	Medium	1930	Building	Dwelling	Front Gable	Asbestos		1-story house with 2-story addition on rear. 1/1 windows
			1970	Domestic	Dwelling	Craftsman	Good	1	
424 S Trojan Street	148	Low	1950	Building	Dwelling	Cross Gable	Asbestos		raised onto posts, windows replaced
			1965	Domestic	Dwelling	Craftsman	Good	2	
100 E White Avenue	193	Medium	1935	Building	Grocery	Front Gable			Souvenir City, originally Loomis (Gaulding) Grocery, damaged by Hurricane Celia in 1970; renovated/altered in 1970s.
			1975	Commercial	Retail		Good	1	
200 block E White Avenue	154	Low	1960	Building	Dwelling	Hip	Wood		on stilts, horizontal aluminum windows
				Domestic	Dwelling		Good	2	
218 E White Avenue	153	Low	1930	Building	Dwelling	Front Gable	Wood/Hardboard		1-story with 2-story addition
			1995	Domestic	Dwelling		Good	1	
300 block E White Avenue	155	Low	1930	Building	Dwelling	Hip	Asbestos/Wood		has large front and side addition
			1965	Domestic	Dwelling		Good	1	
300 block E White Avenue	157	Medium	1920	Building	Dwelling	Pyramidal	Wood (false bevel)		exposed rafter ends
			1970	Domestic	Dwelling	Craftsman	Poor	1	
312 E White Avenue	156	Low	1955	Building	Dwelling	Side Gable	Asbestos		
				Domestic	Dwelling		Good	1	
403 E White Avenue	158	Medium	1940	Building	Dwelling	Cross Gable	Vinyl		louvered windows
			1975	Domestic	Dwelling		Good	1	
420 E White Avenue	159	Medium	1930	Building	Dwelling	Front Gable	Aluminum		louvered windows
			1965	Domestic	Dwelling		Good	1	
100 block W White Avenue	151	Low	1940	Building	Dwelling	Hip	Asbestos		roof changed
				Domestic	Dwelling		Fair	1	
12 W White Avenue	152	Medium	1950	Building	Dwelling	Front Gable	Asbestos		1/1 windows, picture window
				Domestic	Dwelling		Good	1	
128 W White Avenue	150	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		windows replaced
				Domestic	Dwelling		Good	1	